


# MT35A synchronous driver with PC' installation instruction

## XP System

1 Decompress the package to any path on PC.


2 Connect the MT35A to the PC use USB cable. System will notice that a new hardware was found, just like the picture below:

a)




Choose “No, not this time”, then press “Next”.

b)



Choose "Install from a list or specific location(Advanced)", then press "Next"

c)



Choose "Include this location in the search:", press "Browse", then choose the directory "ADB" which was the subdirectory of "USB", press "Ok", then press "Next".


d)




Driver install finished, press "Finish".

## Win7 System


1. Decompress the package to any path on PC.
2. Connect the MT35A to the PC use USB cable. System will notice that Failed to install device driver, Click on it, into the interface of the device manager.If there is no the notice, can open the device manager directly.




3. Click on the Other Devices, Right click Android in the red box, Select the first which is update driver,then choose second red box Through the computer to find the driver software.




4. Choose red box->next




5. Choose ADB Interface->next





6. From the disk to install -> browse .



7. To find unzip the files in the first step \USB(Driver)\ADB\android\_winusb.inf -> Open







8. After the success of the installation, ADB Interface will appear in the device manager.

